
<u>-</u>	<u> </u>
MARYLAND HISTORICAL TRUST	SURVEY NUMBER: AA 1331
21 STATE CIRCLE SHAW HOUSE	NEGATIVE FILE NUMBER:
ANNAPOLIS, MARYLAND 21401	UTM REFERENCES:
HISTORIC SITES SURVEY FIELD SHEET	Zone/Easting/Northing
Individual Structure Survey Form	
	U.S.G.S. QUAD. MAP:
	PRESENT FORMAL NAME:
	Redemptorist's Novitiate House
COUNTY: Anne Arundel	ORIGINAL FORMAL NAME:
TOWN: Annapolis	PRESENT USE: Retreat House/Rectory
LOCATION: 101 Duke of Gloucester	ORIGINAL USE: Retreat House/Rectory
at St. Mary's Church	ARCHITECT/ENGINEER:
COMMON NAME:	DUTE D 70 /00 VET - 00 -00
St. Mary's Rectory FUNCTIONAL TYPE: Res Map 33 Par 158	BUILDER/CONTRACTOR:
OWNER: St. Mary's Catholic Church	PHYSICAL CONDITION OF STRUCTURE:
ADDRESS: Duke of Gloucester Street	Excellent(X) Good()
Annapolis, MD 21401	Fair() Poor:()
ACCESSIBILITY TO PUBLIC: Yes(X) No () Restricted()	THEME: STYLE: Gothic Revival
Yes(X) No () Restricted() LEVEL OF SIGNIFICANCE:	DATE DUTIT.
Local() State $()$ National()	DATE BUILT: c.1860
GENERAL DESCRIPTION:	
Structural System  1. Foundation: Stone()Brick(X)Concrete()Concrete Block()	
2. Wall Structure	
A. Wood Frame: Post and Beam()Balloon()	
B. Wood Bearing Masonry: Brick(X)Stone()Concrete()Concrete Block() C. Iron() D. Steel() E. Other:	
3. Wall Covering: Clapboard()Board and Batten()Wood Shingle()Shiplap()	
Novelty()Stucco()Sheet Metal()Aluminum()Asphalt Shingle()	
Brick Veneer(X)Stone Veneer() Asbestos Shingle()	
Bonding Pattern: Common Other: 4. Roof Structure	
A. Truss: Wood(X)Iron()Steel()Concrete()	
B. Other:	
5. Roof Covering: Slate()Wood Shingle()Asphalt Shingle()Sheet Metal(() Built Up()Rolled()Tile()Other:	
6. Engineering Structure:	
7. Other:	Dormers( )Chimneys/V)Sheds/ \Flls/ \
Appendages: Porches()Towers()Cupolas()Dormers()Chimneys(X)Sheds()Ells() Wings ()Other:	
Roof Style: Gable(X)Hip()Shed()Flat()Mansard()Gambrel()Jerkinhead()	
Saw Tooth()With Monitor( With Bellcast()With Parapet()With False Front()	
Other: Number of Stories: 3	
Number of Bays: Entrance Location: Centered	
Approximate Dimensions: L Plan = 130 x 110	
40' deep	
	LOCAL ATTITUDES
THREAT TO STRUCTURE: No Threat(X)Zoning()Roads()	LOCAL ATTITUDES: Positive()Negative()
Development()Deterioration()	Mixed() Other:
Alteration ( )Other:	

## ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION: Large Gothic Revival structure with corbeled cornice, compound Gothic pointed arches at all windows and entrances, stepped buttresses as pilaster strips define bays at front wall and every five bays at end, molded brick watertable; row of corbeled chimneys at southwest end wall. RELATED STRUCTURES: (Describe) STATEMENT OF SIGNIFICANCE: Excellent example of large scale Gothic Revival, complimenting the exceptional church to the right, with excellent brick details and fenestration pattern; critical to streetscape. REFERENCES: (Indicate North In Circle) SURROUNDING ENVIRONMENT: MAP: Open Lane( )Woodland( )Scattered Buildings( ) Moderately Built Up( )Densely-Built Up(√) Residential()Commercial() Agricultural()Industrial() Roadside Strip Development() Other: RECORDED BY: Russell Wright

ORGANIZATION:

DATE RECORDED:

Historic Annapolis, Inc





St. Mary's Rectory AA 1331
Annapolis, Anne Arundel County
Russell Wright July, 1982
Maryland Historical Trust,

Annapolis, Maryland

NW Elevation/camera facing SE